

STATE OF TEXAS WELL REPORT for Tracking #568314

Owner:	Susan DeKoch	Owner Well #:	No.11 -R05668
Address:	207 Hillview Dr. San Antonio, TX 78209	Grid #:	56-55-8
Well Location:	11802 S. Ranch Road 783 Kerrville, TX 78028	Latitude:	30° 09' 51.58" N
Well County:	Gillespie	Longitude:	099° 10' 48.48" W
		Elevation:	No Data
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: **1/23/2021** Drilling End Date: **1/24/2021**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	14	0	20
	8.75	20	600

Drilling Method: **Air Hammer**

Borehole Completion: **Perforated or Slotted**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	50	Cement 20 Bags/Sacks
	50	240	Benseal 5 Bags/Sacks

Seal Method: **Pumped**

Sealed By: **Driller**

Distance to Property Line (ft.): **350**

Distance to Septic Field or other
concentrated contamination (ft.): **>150**

Distance to Septic Tank (ft.): **>150**

Method of Verification: **GPS**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **380 ft. below land surface on 2021-01-25** Measurement Method: **Electric Line**

Packers: **Rubber at 240 ft.**

Type of Pump: **No Data**

Well Tests: **No Test Data Specified**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
No Data	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **NextGen Water Well Service**
11911 West County Road 56
Midland, TX 79707

Driller Name: **Cody Myers**

License Number: **60303**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	1	Top Soil
2	30	Limestone (Tan)
30	160	Limestone (White)
160	170	Fractured (Gray)
170	215	Tan Limestone
215	228	Grey Sand Stone
228	440	Gray shale and Clay
440	480	Brown Clay
480	500	Cemented Sandstone
500	520	Red Clay
520	545	Brown Sand
545	580	Course Sand and Gravel with Clay Stringers
580	600	Course Sand with Limestone Stringers

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
10	Blank	New Steel		0	20
5	Blank	New Plastic (PVC)	SDR 17	0	510
5	Screen	New Plastic (PVC)	SDR 17 0.025	510	590

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**