

STATE OF TEXAS WELL REPORT for Tracking #568312

Owner: **Susan DeKoch** Owner Well #: **No.9 -R05666**
Address: **207 Hillview Dr.** Grid #: **56-55-8**
San Antonio, TX 78209
Well Location: **11802 S. Ranch Road 783** Latitude: **30° 09' 44.66" N**
Kerrville, TX 78028 Longitude: **099° 11' 31.13" W**
Well County: **Gillespie** Elevation: **No Data**

Type of Work: **New Well** Proposed Use: **Domestic**

Drilling Start Date: **1/28/2021** Drilling End Date: **1/29/2021**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	14	0	20
	8.75	20	600

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	50	Cement 20 Bags/Sacks
	50	200	Bentonite 19 Bags/Sacks

Seal Method: **Pumped**

Sealed By: **Driller**

Distance to Property Line (ft.): **550**

Distance to Septic Field or other
concentrated contamination (ft.): **>150**

Distance to Septic Tank (ft.): **>150**

Method of Verification: **GPS**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **400 ft. below land surface on 2021-02-01** Measurement Method: **Electric Line**

Packers: **Rubber at 197 ft.**

Type of Pump: **No Data**

Well Tests: **No Test Data Specified**

Water Quality:	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
	No Data	No Data

Chemical Analysis Made: **Yes**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **NextGen Water Well Service**
11911 West County Road 56
Midland, TX 79707

Driller Name: **Cody Myers** License Number: **60303**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	2	Top Soil
2	80	Limestone (Soft)
80	135	Limestone (White)
135	380	Gray Shale and Clay
380	400	Brown Clay
400	420	Red Clay
420	450	Brown Sandy CLay
450	480	Gray Clay with Sandstone stringers
480	560	Sand with Sandstone Stringers
560	600	Sand with Limestone Stringers

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
10	Blank	New Steel		0	20
5	Blank	New Plastic (PVC)	SDR 17	0	520
5	Screen	New Plastic (PVC)	SDR 17 0.025	520	600

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**