

Water Quality:

Strata Depth (ft.)	Water Type
No Data	No Data

Chemical Analysis Made: **Yes**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **NextGen Water Well Service**
11911 West County Road 56
Midland, TX 79707

Driller Name: **Cody Myers**

License Number: **60303**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Top Soil
1	9	Clay
9	65	Tan Limestone
65	125	White Limestone
125	130	Gray Limestone
130	140	Gray Sand Stone and Clay
140	380	Gray shale and Clay
380	390	Brown Clay
390	465	Cemented Course Sandstone
465	525	Course Sand wit Clay Stringers
525	540	Brown Clay
540	590	Red Sand with Limestone Stringers

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
10	Blank	New Steel		0	20
5	Blank	New Plastic (PVC)	SDR 17	0	500
5	Screen	New Plastic (PVC)	SDR 17 0.025	500	579

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**